

QUARRY ASSESSMENT CERTIFICATE

CERTIFICATE NUMBER S106 **ISSUE DATE** 16 April 2007
EXPIRY DATE 16 April 2009

QUARRY NAME Mount Sylvia

DMR QUARRY REFERENCE 3/114/9

QUARRY LOCATION
District Southern
Shire Gatton
Real Property Description Lot 124 SP176970 & Lot 166 on CC493 Parish of East Haldon
AMG
or *MGA* Zone 56 417000E 6922100N

NOMINATED PRODUCTS Asphalt Aggregate (excepting wearing course), Cover Aggregate (Types A B C D), Concrete Aggregate, Railway Ballast (Types 2 3), Slurry Seal Aggregate, Unbound Paving Material (Type 3)

COMMENTS

ROCK TYPE / ROCK MATERIAL GROUP Olivine Basalt / Basic Igneous

APPLICANT NAME Mt Sylvia Diatomite Pty Ltd
APPLICANT'S ADDRESS Chalk Mine Rd, Junction View via Gatton Qld 4343

QUARRY OWNER Mt Sylvia Diatomite Pty Ltd

NOMINATED OPERATOR Mt Sylvia Diatomite Pty Ltd
OPERATOR'S ADDRESS PO Box 448 Gatton Qld 4343

APPROVER'S SIGNATURE

Regional Geologist (Southern)

NOTES

Departmental Quarry Certification indicates the following:

- The Quarry assessment submitted by the Applicant has been evaluated by a Departmental Geologist and complies with the assessment standards outlined in Section 5 of Engineering Policy EP108.
- The source rock properties as described in the submitted assessment are generally superior to those required in the relevant specifications for the nominated product or products.

Departmental Quarry Certification does not guarantee product compliance with Department Specifications since this is influenced by many operational factors such as extraction and production procedures and source material variability.